



Photo 1 – Main Wreckage (Photo Courtesy of FAA)




Photo 2 – Fractured Engine Mounts (Photo Courtesy of FAA)