

ERA22LA345

INVESTIGATION PHOTOGRAPHS



Photograph 1 -View of ground scars and airplane. (Courtesy of FAA)



Photograph 2 - Right profile view of airplane damage. (Courtesy of FAA)



Photograph 3 - Right front quarter view of right wing and airframe damage. (Courtesy of FAA)