



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA348



Photo 1 – View of airplane from right front (Photo courtesy of FAA)



Photo 2 – View of airplane from right rear (Photo courtesy of FAA)



Photo 3 – View of damage near right main landing gear (Photo courtesy of FAA)



Photo 4 – View of fractured right main landing gear upper fitting (Photo courtesy of FAA)



Photo 5 – View of fractured right main landing gear lower attachment points (Photo courtesy of FAA)



Photo 6 – View of cockpit from cabin



Photo 7 – View from left pilot seat toward rear of airplane




Photo 9 – View of lower fitting bolts for right main landing gear (Photo courtesy of Airbus)



Photo 10 – View of fractured right main landing gear as configured for recovery and ferry