



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA358




Photo 1 – View of rudder cable pulley with orange deposits (Photo Courtesy of FAA)



Photo 2 – View of rudder cable pulley with orange deposits as seen from above. (Photo Courtesy of FAA)



Photo 3 – View of fractured left rudder cable (Photo Courtesy of FAA)