



Photo 1 – Right wing leading edge damaged, (FAA)



Photo 2 – Bent spar (FAA)