

ERA22LA378

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane submerged in saltwater (Courtesy of FAA)



Photograph 2 - View of airplane after recovery (Courtesy of FAA)



Photograph 3 - View of instrument panel (Courtesy of FAA)



Photograph 4 - View of cockpit switches (Courtesy of FAA)



Photograph 5 - View of engine with cowling removed (Courtesy of FAA)