

ERA22LA404

IIC INVESTIGATIVE PHOTOGRAPHS

Photo Array¹

August 19, 2024

¹ It could not be determined in the following photographs taken following recovery if the damage occurred as a result of the initial touchdown or subsequent movement of the airplane with one passenger remaining inside.



Photo 1: NTSB Digital Photograph. Left Side View of the Airplane Following Recovery.



Photo 2: NTSB Digital Photograph. Right Side View of the Airplane Following Recovery.



Photo 3: NTSB Digital Photograph. Left Side View of the Aft Empennage.



Photo 4: NTSB Digital Photograph. Right Side View of the Aft Empennage.



Photo 5: NTSB Digital Photograph. View of the Instrument Panel and Portion of Co-Pilot Seat.



Photo 6: NTSB Digital Photograph. Left Side View of the Front Pressure Bulkhead, and Fuselage Immediately Aft of it.



Photo 7: NTSB Digital Photograph. Frontal View Looking Aft to Front Pressure Bulkhead. Note the Extensive damage.



Photo 8: NTSB Digital Photograph. Right Side View of the Front Pressure Bulkhead, and Fuselage Immediately Aft of it.