



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA408



Photo 1 – View of Airplane Dataplate (Courtesy of FAA)



Photo 2 – View of Empennage Left Side (Courtesy of FAA)



Photo 3 – Closeup View of Stringer Damage (Courtesy of FAA)



Photo 4 – Closeup View of Stringer Damage (Courtesy of FAA)