



Photo 1 – FAA Digital Photograph. Left Forward Quartering View of the Airplane Following Recovery. Note the Separated Aft Empennage.



Photo 2 – FAA Digital Photograph. View of the Structurally Damaged Aft Empennage.



Photo 3 - FAA Digital Photograph. View Showing the Open Exhaust Valve of the No. 2 Cylinder.