



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA415



Photo 1 – View of Accident Airplane (Courtesy of FAA)



Photo 2 – View of Airplane Underside – note damage (Courtesy of FAA)



Photo 3 – Closeup View of Fuselage Damage – note bent frame (Courtesy of FAA)