



Photo 1 – main wreckage (Pilot)



Photo 2 – main wreckage, main rotor bent (Pilot)