

ERA22LA434

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of the accident airplane with a collapsed nose landing gear on the runway
(Photo courtesy of FAA)**



Photograph 2 - Overview of the substantial damage sustained to the fuselage (Photo courtesy of FAA)



Photograph 3 - View of the disconnected NLG torque tube (reportedly disconnected by maintenance personnel after the accident) (Photo courtesy of FAA)



Photograph 4 - Landing gear actuator arm (Photo Courtesy of FAA)



Photograph 5 - View of the landing gear indicator lights displaying all three gear down and locked postaccident (Photo Courtesy of FAA)



**Photograph 6 - View of the landing gear manual hand crank found in an intermediate position
(Photo Courtesy of FAA)**