

ERA23FA087

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of inverted airplane from right wing



Photograph 2 - View of inverted airplane from rear



Photograph 3 - View of inverted airplane from left wing (note missing aileron and wingtip)



**Photograph 4 - View of inverted airplane from front
(note putty on left wing fuel vent to stop leakage)**



Photograph 5 - View of empennage, tree impact scars, and tree debris



Photograph 6 - View of up-righted airplane before examination



Photograph 7 - View of up-righted airplane before examination



Photograph 8 - Left wing fracture with damage consistent with tree impact



Photograph 9 - Left wing damage consistent with tree impact




Photograph 10 - Fuel leakage from left wing fuel vent stopped with putty



Photograph 11 - Left wing fuel bladder with visible fuel



Photograph 12 - Right wing absent of any fuel staining



Photograph 13 - Right wing fuel bladder with no visible fuel



Photograph 14 - Fuel selector with right main tank selected