

ERA23FA108

Accident Site Map 1

Legend

 Wreckage and Features

Right Wingtip First Tree Strike Left Flap Left Main Landing Gear
Left Outboard Wing Sections Right Flap Right Wing Root Left Inboard Wing Root and Wheel Well
Outboard Portion of Right Stabilator Right Forward Fuselage Lower Door Frame Propeller Oil Dome
Upper Engine Cowling Lower Right Portion of Cowling
Forward Cabin Door Piece of Right Aileron
Broken Tree Inboard Portion of Left Wing Spar
Vertical Stabilizer and Rudder
Forward Portion of Cockpit Brow
Propeller
Aft Cabin
Right Wing
Forward Cabin and Engine (Main Wreckage)



100 ft

ERA23FA108

Accident Site Map 2

Legend

 Wreckage and Features

Right Wingtip
First Tree Strike
Left Flap
Left Main Landing Gear
Right Flap
Left Outboard Wing Sections
Left Inboard Wing Root and Wheel Well
Outboard Portion of Right Stabilator
Right Forward Fuselage Lower Door Frame
Upper Engine Cowling
Lower Right Portion of Cowling
Propeller Oil Dome
Forward Cabin Door
Piece of Right Aileron
Broken Tree
Inboard Portion of Left Wing Spar
Vertical Stabilizer and Rudder
Forward Portion of Cockpit Brow
Propeller
Aft Cabin
Right Wing



60 ft

ERA23FA108

Accident Site Map 3

Legend

 Wreckage and Features



60 ft

Google Earth