

ERA23FA108

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site



Photograph 2 - Accident Site



Photograph 3 - Propeller Strike



Photograph 4 - Tree Trunk Impression



Photograph 5 - Propeller Strike



Photograph 6 - Engine



Photograph 7 - Landing Gear Switch



Photograph 8 - Magneto Switch



Photograph 9 - Throttle Quadrant



Photograph 10 - Flap Handle




Photograph 11 - Cabin



Photograph 12 - Right Wing



Photograph 13 - Forward Cabin Door



Photograph 14 - Engine Fuel Servo



Photograph 15 - Fuel Distribution Manifold



Photograph 16 - Spark Plug



Photograph 17 - Propeller




Photograph 18 - Control Cable



Photograph 19 - Wreckage Layout Overview



Photograph 20 - Pitot Mast



Photograph 21 - Oil Filter Media