

ERA23FA209

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage Site (NTSB Photo)



Photograph 2 - Main Wreckage (NTSB Photo)



Photograph 3 - Left Wing and Carry Through (NTSB Photo)



Photograph 4 - Left Wing and Carry Through (NTSB Photo)



Photograph 5 - Separated Right Wing Section (Courtesy of Textron)



Photograph 6 - Engine (NTSB Photo)



Photograph 7 - Propeller Assembly (NTSB Photo)