



Office of Aviation Safety
Eastern Region

Photo Array

ERA23FA238



Photo 1 – View of burned airplane wreckage from rear.



Photo 2 – View of empennage.



Photo 3 – View of airplane engine.



Photo 4 – View of hole in engine crankcase.