



Photo 1 – Main wreckage, front view



Photo 2 – Main wreckage



Photo 3 – Main wreckage, view from left wing, note accordion crushing on leading edge



Photo 4 – Instrument panel



Photo 5 - Engine