

ERA23FA270

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Initial Impact Point (NTSB Photo)



Photograph 2 - Initial Ground Impact (NTSB Photo)



Photograph 3 - Left Wing Outboard (NTSB Photo)



Photograph 4 - Right Wing (NTSB Photo)



Photograph 5 - Left Engine (NTSB Photo)



Photograph 6 - Right Engine (NTSB Photo)



Photograph 7 - Left Propeller (NTSB Photo)



Photograph 8 - Right Propeller Blade (NTSB Photo)



Photograph 9 - Propeller Blade Damage to Tree (NTSB Photo)



Photograph 10 - Engine Tachometer (NTSB Photo)



Photograph 11 - Forward Fuselage and Cockpit (NTSB Photo)



Photograph 12 - Attitude Gyro Case (NTSB Photo)