

ERA23FA273

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site



Photograph 2 - Main Wreckage



Photograph 3 - Oil Streaks on Empennage



Photograph 4 - Engine And Propeller



Photograph 5 - Hole in Top of Crankcase



Photograph 6 - Loose Oil Sump Accessory Port Plug



Photograph 7 - Blue Staining Below Engine