



Photo 1 – Main wreckage, inverted 50 ft up a tree



Photo 2 – Main wreckage, on ground



Photo 3 – left wing tip damaged



Photo 4 – Rudder damaged