


ERA23FA357

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of wreckage resting in water with location details. Note oil mats to prevent fuel and oil from escaping into waterway. (NTSB IIC)



Photograph 2 - View of wreckage from opposing tributary bank. (Courtesy of Robinson)



Photograph 3 - View of wreckage during recovery from water. (NTSB IIC)



**Photograph 4 - View of rotor head and blades. Note, blades were cut off to facilitate recovery.
(Courtesy of Robinson)**



Photograph 5 - View of rotor blades on hanger floor. (NTSB IIC)



Photograph 6 - View looking forward of severed tail boom and control rod. (NTSB IIC)



Photograph 7 - View of dam and river where the photographer was standing. (NTSB IIC)