

ERA23FA382

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Left side view of wreckage
(Courtesy of NTSB)**



**Photograph 2 - Caption of photograph
(Courtesy of NTSB)**



**Photograph 3 -Right side airplane wreckage
(Courtesy of NTSB)**



**Photograph 4 - Engine mounts with non-standard washers
(Courtesy of NTSB)**



**Photograph 5 -Left engine upper bushing
(Courtesy of NTSB)**



**Photograph 6 - Right engine upper bushing
(Courtesy of NTSB)**



**Photograph 7 - Nonstandard upper engine mount washers
(Courtesy of NTSB)**