



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA030



Photo 1 – View of Left Wing Damage (Photo Courtesy of PJ Mills)



Photo 2 – View of Airplane from Rear (Photo Courtesy of PJ Mills)



Photo 3 – View of Ground Scars (Photo Courtesy of PJ Mills)