

ERA23LA035

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane after recovery from water (Courtesy of FAA)



Photograph 2 - Airplane from aft left, note damage to ruddervator (Courtesy of FAA)



Photograph 3 - Fuel recovered from both wings (Courtesy of Atlanta Air Recovery)



Photograph 4 - Damaged ruddervator (NTSB)