

ERA23LA037

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of the airplane at the accident site (Courtesy of FAA)



Photograph 2 - Image of the thermally damaged cowling (Courtesy of FAA)



Photograph 3 - Image of substantially damaged rudder (Courtesy of FAA)