

ERA23LA058

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Side View of Main Wreckage (Courtesy of FAA)



Photograph 3 - Close Up of Outboard Sections of Lower and Upper Outboard Right Wing Sections (Courtesy of FAA)




Photograph 4 - Propeller



Photograph 5 - Oil Cooler



Photograph 6 - Instrument Panel



Photograph 7 - Cylinder Head Temperature Gauge



Photograph 8 - Oil Cooler and Cowl Flap Switches



Photograph 9 - Metallic Particles



Photograph 10 - Close Up of Metallic Particles