

ERA23LA064

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Lower Fuselage Skin and Structure Damage (Courtesy of FAA)



Photograph 2 - Lower Fuselage Skin and Structure Damage (Courtesy of FAA)



Photograph 3 - Propeller Damage (Courtesy of FAA)