

ERA23LA065


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of fire damaged airplane. (Courtesy of FAA)



Photograph 2 - View of engine compartment alternator wire. (Courtesy of FAA)



Photograph 3 - View of alternator wire damage. (Courtesy of FAA)



Photograph 4 - View of engine mount electrical arc damage. (Courtesy of FAA)