



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA076



Photo 1 – View of Ultralight at Accident Site – Note N-Number and Wreckage is Inverted (Courtesy of FAA)



Photo 2 – View of Ultralight from Rear (Courtesy of FAA)



Photo 3 – View of Ultralight’s Front Left Side – Note Ultralight is Inverted (Courtesy of FAA)