



Photo 1 – View of airplane from the front showing damage to engine cowling (FAA Photo)



Photo 2 – View of airplane from right side showing damage to right wing (FAA Photo)