







RT WS 187.55


Cape Air

Cessna 402C

N26407








LE RIB at RT WS 187.55
Bonded cap section cracked
View is OB looking IB



LE RIB at RT WS 187.55
Bonded cap section cracked
View is OB looking IB

This photograph shows a close-up of a yellow-painted aircraft wing rib. The rib is curved and features several silver-colored rivets. A section of the bonded cap, which is a thin layer of material on the upper surface of the rib, is visibly cracked and peeling away. The crack runs along the length of the rib. The background is a dark, textured surface, likely the interior of the wing structure. The text overlay provides specific location and inspection details.



LE RIB at RT WS 187.55
Upper and LWR bonded cap sections
are de-bonded
View is IB looking OB