



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA111



Photo 1 – View of Engine Cowling (Courtesy of Operator)



Photo 2 – Closeup of Damage to Rear Side of Propellor Blade (Courtesy of Operator)