



Photo 1 – View of Runway Departure End, Ground Tracks, Berm, and Airplane at Rest Where Found (FAA)



Photo 2 – View of Airplane Facing Opposite Direction of Travel (FAA)



Photo 3 – View of Damage to Nose Compartment (FAA)




Photo 4 – View of Engine Uncrated in Examination Room (Lycoming)




Photo 5 – View of #5 Piston with Broken Connecting Rod inside #5 Cylinder (Lycoming)



Photo 6 – View of #5 Piston Displaying Damage Signatures Consistent with Detonation (Lycoming)




Photo 7 – View of Extruded Crankshaft Nose Seal (Lycoming)