



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA116



Photo 1 – View of Airplane Prior to Accident (Courtesy of Pilot)



Photo 2 – View of Lift Strut Attachment Damage – Note Area Circled (Courtesy of Pilot)



Photo 3 – View of Left Wing, Rear Spar Damage (Courtesy of Pilot)