

ERA23LA120

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Propeller Strike Marks on Displaced Threshold (Courtesy of FAA)



Photograph 2 - Close Up of Propeller Strike Marks (Courtesy of FAA)



Photograph 3 - Tire Tracks / Skid Marks (Courtesy of FAA)



Photograph 4 - main Wreckage (Courtesy of FAA)



Photograph 5 - Close Up of Cabin Area (Courtesy of FAA)



Photograph 6 - Propeller and Engine Cowling



Photograph 7 - Engine



Photograph 8 - Fuel Selector Valve



Photograph 9 - No.3 Bottom Spark Plug and Spark Plug Hole (Courtesy of Lycoming Engines)



Photograph 10 - Close Up of No.3 Bottom Spark Plug



Photograph 11 - No.3 Bottom Spark Plug Hole and Helicoil



Photograph 12 - Close Up of No.3 Bottom Spark Plug Hole and Helicoil