

ACCIDENT N107DF

AERO COMMANDER 500B

DAMAGED ASSESSMENT

On January 28, 2023, about 17:40 CST a twin-engine aero commander 500-b airplane, N107DF, experience a loss of engine power during cruise flight enroute to (KBHM) after departure from (KVDF).

Pilot landed in open field airplane impacted trees and bob-wire fenced coming to rest on belly of fuselage. Left wing and engine separated from airplane left wing severely damaged. Right wing severely damaged and partially separated from airplane. Both wing fuel bladders were breach with minor fuel leakage notice on ground adjacent to wing. Right wing engine propeller bent. Left Engine cowlings damaged and Right Engine spinner and cowlings damaged. Fuselage of airplane showed punctured holes and dents on both sides forward and aft of aircraft. Airplane was substantially damaged.