

NTSB ERA23LA124

N330PC, RV-6

Photo Array



Photo 1: View of the airplane at the accident site (Photo Courtesy of FAA)



Photo 2: View of the propeller and airplane at the accident site (Photo Courtesy of FAA)



Photo 3: View of the tail of the airplane at the accident site (Photo Courtesy of FAA)



Photo 4: View of the left wing under the fuel truck. (Photo Courtesy of FAA)



Photo 5: View of the right fuel tank fuel pickup and fuel sending unit (Photo Courtesy of Florida Air Recovery)



Photo 6: View of left fuel tank fuel pickup and sending unit (Photo Courtesy of Florida Air Recovery)