

NTSB ERA23LA125

N116CL, Diamond DA-20-C1

Photo Array




Photo 1: Overview of the airplane center spar delamination damage (red circled #1) (Photo Courtesy of FAA)



Photo 2: Overview of the airplane's fuselage damage (Photo Courtesy of FAA)



Photo 3: Main Landing gear which sheared off during collapse (Photo Courtesy of FAA)