



Photo 1 – View of right wight damage (FAA Photo)



Photo 2 – Left side of fuselage (FAA Photo)



Photo 3 – View of Fuel removed from fuel strainer (FAA Photo)



Photo 4 – view carburetor fuel screen (FAA Photo)