

NTSB ERA23LA139

N2419V, Cessna 140

Photo Array



Photo 1: Overview of the airplane as it lay in the field (Photo Courtesy of FAA)



Photo 2: Overview of the airplane as it lay in the field with damage to the fuselage, vertical stabilizer and rudder (Photo Courtesy of FAA)



Photo 3: Overview of the airplane at the accident site (Photo Courtesy of FAA)



Photo 3: Overview of the airplane in a hangar after recovery with damage to the wings and tail (Photo Courtesy of FAA)