



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA140



Photo 1 – View of Accident Airplane from Front Right – Note Cowling and Propellor Removed (Courtesy of FAA)



Photo 2 – Closeup View of Right Wing Underside Damage – Note Composite Materials (Courtesy of FAA)



Photo 3 – View of Right Wing Underside, Removed From Fuselage and Upright (Courtesy of FAA)