

ERA23LA148

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Main Wreckage (Courtesy of Tow Boat US)




Photograph 2 - Wreckage Recovered (Courtesy of FAA)



Photograph 3 - Engine And Propeller (Courtesy of FAA)



Photograph 4 - Underside of Engine (Courtesy of FAA)



Photograph 5 - EIS Test (Courtesy of NTSB)