



Photo 1 – View of Airplane as Found (FAA)




Photo 2 – View of Upper Bellcrank Overtravel and Damaged Down-Limit Switch (Thoroughbred Aviation)



Photo 3 – View of Bent Landing Gear Switch Mount (Thoroughbred Aviation)



Photo 4 – Profile View of Bent Down-Lock Switch Mount (Thoroughbred Aviation)




Photo 5 – View of Exemplar Landing Gear Motor in Retracted Position (Textron)




Photo 6 – View of Exemplar Landing Gear Motor in Extended Position (Textron)




Photo 7 – View of Landing Gear Motor and Damaged Switch from ERA16LA271 (FAA)