

NATIONAL TRANSPORTATION SAFETY BOARD

NTSB Form 6120.1

PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

Email the pilot/operator aircraft accident/incident report to the investigator-in-charge of your accident/incident. If email is not available, mail the report per the instructions below.

If your accident/incident occurred in Maine, Vermont, New Hampshire, Massachusetts, Connecticut, Rhode Island, New York, New Jersey, Pennsylvania, Maryland, Delaware, Virginia, West Virginia, Kentucky, Tennessee, North Carolina, South Carolina, Mississippi, Alabama, Georgia, Florida, the District of Columbia, Puerto Rico, or the US Virgin Islands, send the form to: NTSB, ERA, 45065 Riverside Parkway, Ashburn, VA 20147.

If your accident/incident occurred in Ohio, Michigan, Indiana, Wisconsin, Illinois, Minnesota, Iowa, Missouri, Arkansas, Louisiana, North Dakota, South Dakota, Nebraska, Kansas, Oklahoma, Texas, Colorado, or New Mexico, send the form to: NTSB, CEN, 4760 Oakland Street, Suite 500, Denver, CO 80239.

If your accident/incident occurred in Montana, Wyoming, Idaho, Utah, Arizona, Nevada, Washington, Oregon, California, Hawaii, or the territories of Guam or American Samoa, send the form to: NTSB, WPR, 505 South 336th Street, Suite 540, Federal Way, WA 98003.

If your accident/incident occurred in Alaska, send the form to: NTSB, ANC, 222 West 7th Avenue, Room 216, Box 11, Anchorage, AK 99513.

Rules pertaining to notification of aircraft accidents and incidents, as well as overdue aircraft are found in 49 *Code of Federal Regulations* (CFR) Part 830 http://www.ecfr.gov/cgi-bin/text-idx?c=ecfr&tpl=/ecfrbrowse/Title49/49cfr830_main_02.tpl. These rules state the authority of the NTSB, define accidents, incidents, injuries, and other terms, and provide procedures for initial and immediate notification of accidents and incidents by aircraft pilots/operators.

A. APPLICABILITY

The pilot/operator of an aircraft shall send a report to the office listed above, based on accident/incident location; immediate notification is required by 49 CFR 830.5(a). **The report shall be filed within 10 days after an accident for which notification is required by Section 830.5, or after 7 days if an overdue aircraft is still missing.**

An aircraft accident, as defined in 49 CFR 830.2, is determined as an occurrence that involves a fatality or serious injury, or substantial damage to the aircraft. For occurrences that do not involve a fatality, the determination that the occurrence is an accident can be appealed by writing to the Director, Office of Aviation Safety, NTSB, 490 L'Enfant Plaza, S.W., Washington, D.C. 20594.

INSTRUCTIONS TO PILOTS/OPERATORS FOR COMPLETING THIS FORM

It is necessary that ALL questions on this report be answered completely and accurately.

If more space is needed, continue on a blank sheet of paper.

Nearest City/Place: Use the name of the nearest community in the state where the accident/incident occurred.

Date/Time: Indicate the date and local time of the event. Be sure to indicate the time zone.

Phase of Operation: Indicate the phase of operation during which the accident/incident occurred.

Aircraft Information: Enter aircraft make and model information as indicated on the aircraft registration certificate, including series. If the involved aircraft is certified as "amateur-built," include the name of the producer of the kit or plans, unless an NTSB employee instructs otherwise.

Maximum Gross Weight: Enter the certificated maximum gross weight for the aircraft involved in the occurrence. This should be the same as the maximum gross weight indicated on the aircraft weight and balance documents.

Engine: Enter engine make and model information as indicated on the engine data plate.

The NTSB uses this form for aircraft accident prevention activities and for statistical purposes. NTSB regulations (49 CFR Part 830) require that **ALL** questions be answered completely and accurately. Completion of this form will take approximately 60 minutes. The NTSB does not guarantee the privacy of any information provided in this form. You need not complete this form unless it displays a valid OMB control number, in accordance with 5 C.F.R. § 1320.5(b), which applies to this collection of information.

B. DEFINITIONS

1. "Aircraft Accident" means an occurrence associated with the operation of an aircraft that takes place between the time any person boards the aircraft with the intention of flight and all such persons have disembarked, and in which any person suffers death, or serious injury, or in which the aircraft receives substantial damage. For purposes of this form, the definition of "aircraft accident" includes "unmanned aircraft accident," as defined at 49 CFR 830.2.

2. "Substantial Damage" means damage or failure that adversely affects the structural strength, performance or flight characteristics of the aircraft, and that would normally require major repair or replacement of the affected component. NOTE: Engine failure or damage limited to an engine if only one engine fails or is damaged, bent fairing or cowling, dented skin, small puncture holes in the skin or fabric, ground damage to rotor or propeller blades, and damage to landing gear, wheels, tires, flaps, engine accessories, brakes, or wing tips are not considered "substantial damage" for purposes of this report.

3. "Operator" means any person who causes or authorizes the operation of an aircraft, such as the owner, lessee, or bailee of an aircraft.

4. "Fatal Injury" means any injury that results in death within thirty (30) days of the accident.

5. "Serious Injury" means any injury that (1) requires hospitalization for more than 48 hours, commencing within 7 days from the date the injury was received; (2) results in a fracture of any bone (except simple fracture of fingers, toes, or nose); (3) causes severe hemorrhages, nerve, muscle, or tendon damage; (4) involves injury to any internal organ; or (5) involves second- or third-degree burns, or any burns affecting more than 5 percent of the body surface.

Type of Fire Extinguishing System: If a fire extinguishing system was used to fight an aircraft fire, specify the type(s) of extinguishing system(s) used. Examples include handheld extinguisher, engine fire bottle, cargo/baggage compartment fire suppression system, or airport emergency ground equipment.

Owner/Operator Information: Enter the owner information as shown on the registration certificate. Commercial operators, enter the operator information, including "doing business as" when applicable, as shown on the operator certificate.

Revenue Sightseeing Flight: Indicate whether the accident aircraft was conducting **revenue** sightseeing operations under 14 CFR Part 91 at the time of the accident.

Air Medical Flight: Indicate whether the accident flight was being conducted for the purpose of carrying medical personnel, patient(s), or organs.

Public Aircraft: Federal, state or local government flight operations such as official travel, law-enforcement, low-level observation, aerial application, firefighting, search and rescue, biological or geological resource management, or aeronautical research. Indicate whether the flight was conducted by the armed forces, federal, state, or local government.

Purpose of Flight: 14 CFR Parts 91, 103, 133, 136, and 137: Indicate the type of operation that was being conducted at the time of the occurrence using the following definitions:

AERIAL APPLICATION--Operations using an aircraft to perform aerial application or dispersion of any substance. Examples include agricultural, health, forestry, cloud seeding, firefighting, insect control, etc.

AERIAL OBSERVATION--These flights include aerial mapping/photography, patrol, search and rescue, hunting, highway traffic advisory, ranching, surveillance, oil and mineral exploration, criminal pursuit, fish spotting, etc.

AIR DROP--Aerial operations, other than aerial application, that are intended to release items in flight.

AIR RACE/SHOW--Includes any flight operations conducted as part of an organized air race or public demonstration.

BUSINESS--includes all personal flying without a paid professional crew for reasons associated with furthering a business, including transportation to and from business meetings or work. This does not include corporate/executive operations, air taxi, or commuter operations.

EXECUTIVE/CORPORATE--Company flying with a paid, professional crew.

FERRY--Non-revenue flight under a special flight or "ferry" permit. Refer to 14 CFR 21.197 for details of special flight permit issuance.

FLIGHT TEST--Flight for the purpose of investigating the flight characteristics of an aircraft/aircraft component or evaluating an applicant for a pilot certificate or rating.

INSTRUCTIONAL--Flying while under the supervision of a flight instructor or receiving air carrier training. Personal proficiency flight operations and personal flight reviews, as required by federal air regulations, are excluded.

OTHER WORK USE--Miscellaneous flight operations conducted for compensation or hire such as construction work (not 14 CFR Part 135 operation), parachuting, aerial advertising, towing gliders, etc.

PERSONAL--Flying for personal reasons (excludes business transportation) including pleasure or personal transportation. This also includes practice or proficiency flights performed under flight instructor supervision and not part of an approved flight training program.

POSITIONING--Non-revenue flight conducted for the primary purpose of relocating the aircraft. Examples include moving the aircraft to a maintenance facility or to load passengers or cargo etc.

UNKNOWN--Use only if the primary purpose of flight is not known.

Other Aircraft--Collision: For all accidents involving a collision with another aircraft, including parked aircraft, check "Collision with other aircraft" under Basic Information and complete this section indicating details about the OTHER aircraft involved in the collision.

Airport Information: Complete this section if the accident/incident occurred on approach, landing, takeoff, departure, or within 3 statute miles of an airport. Please refer to the FAA Airport/Facility Directory or other official source for airport information.

Airport Identifier: Provide the official 3 or 4 character airport identifier number.

Runway: Indicate the number of the runway used, including L, R, or C if applicable.

Runway/Landing Surface: Indicate the type of intended runway/landing surface (do not indicate surface conditions). If the surface type was mixed, check all that apply.

Condition of Runway/Landing Surface: Indicate the condition of the intended runway/landing surface. If multiple conditions existed at the time of the accident, check all that apply.

Weather Information at the Accident/Incident Site: Indicate the weather conditions reported at the accident/incident site at the time of occurrence. If no weather reporting was available for the accident/incident site, indicate the reported conditions at the nearest reporting site. Specify the weather reporting site identifier, the observation time, and distance from the accident/incident.

Sky/Lowest Cloud Condition: Indicate the height above ground level of the lowest cloud condition present at the time of the accident/incident and whether coverage was reported as few, scattered, broken or overcast. Also indicate the height above ground level and coverage of the lowest cloud ceiling present at the time of the accident/incident (reported as broken or overcast).

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs: Describe all NOTAMs (distant (D) or Flight Data Center (FDC), if known), AIRMETs, SIGMETs, and PIREPs in effect near the accident/incident.

Flight Crewmember Information: Indicate the category that best describes the capacity served by this flight crewmember at the time of the accident. The designators "Flight Crewmember 1" and "Flight Crewmember 2" do not refer to a specific pilot position or responsibility. If more than one pilot is aboard, they may be entered in any order and their capacity entered as appropriate.

Degree of Injury: See Definitions on the top half of Page 1 of the instructions. Minor injury is not defined. If an injury does not meet the criteria for another injury category, select Minor.

Date of Last Flight Review or Equivalent: Enter the date of the most recent flight review, or equivalent, completed by this pilot. Refer to 14 CFR 61.56 for accepted equivalents.

Type Ratings: List all type ratings on the pilot certificate. If the pilot holds no type ratings indicate "none." If the pilot holds a pilot certificate other than student and was flying an aircraft requiring an endorsement, enter the type and date of any logbook endorsement(s) for that aircraft. See 14 CFR 61 for examples of required endorsements.

Student Endorsements: If the pilot holds a student pilot certificate, enter all solo endorsements and dates on the student pilot certificate.

Flight Time: Complete the flight time matrix. Solo flight time should be included as "Pilot-in-Command (PIC)" and all dual flight instruction given should be included as "Time as Instructor."

Additional Flight Crewmembers: Complete this section if there were more than two required flight crewmembers on the aircraft. This also includes a check airman performing official duties but does not include cabin crew. State the capacity served by each included crewmember at the time of the accident.

Passenger(s)/Other Personnel: Enter identification and injury severity information for all passengers, cabin crew, and other personnel involved in the accident. See Page 1 of the instructions for the official definition of injury levels.

Several questions throughout the form allow for multiple responses; when appropriate, choose all responses that apply.

These instructions only pertain to major issue areas covered by NTSB Form 6120.1 Pilot/Operator Aircraft Accident/Incident Report. For additional definitions of questions and responses, please refer to www.nts.gov.

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Tuskegee State: AL

ZIP: 36083 Country: USA

Latitude: 32° 27 ' 37.7 " N Longitude: 85° 40 ' 48.1 " W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 10/27/2022 Local Time: 1509
mm/dd/yyyy

Time Zone: CDT

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N858AU

Manufacturer: TEXTRON AVIATION INC

Model: 172S

Serial Number: 172S12149

Year of Manufacture: 2018

Amateur-Built: ☐ Yes ☒ No **If Yes:** ☐ Kit/Plans ☐ Original Design Make: _____

☒ **IFR-Equipped and Certified**

☐ **Commercial Space Flight**

☐ **Unmanned Aircraft**

Maximum Gross Weight: 2550 lbs

Weight at Time of Accident/Incident: 2340.62 lbs

Number of Seats: 4 Flight Crew Seats: _____

Cabin Crew Seats: _____ Passenger Seats: _____

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle
- ☐ Amphibian
- ☐ Emergency Float
- ☐ Float
- ☐ Hull
- ☐ Other Launch/Recovery System
- ☐ None
- ☐ Tailwheel
- ☐ High Skid
- ☐ Skid
- ☐ Ski
- ☐ Ski/Wheel
- ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Turbo Shaft
- ☐ Turbo Prop
- ☐ Turbo Jet
- ☐ Turbo Fan
- ☐ Electric
- ☐ Liquid Rocket
- ☐ Solid Rocket
- ☐ Hybrid Rocket
- ☐ None
- ☐ Unknown

Fuel System Type (Reciprocating)

- ☐ Carburetor
- ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Serial	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Lycoming	IO-360-L2A	L-37423-51E	04/25/2018	180	2197.9	85.7	2197.9
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☒ 100-Hour
- ☐ AAIP
- ☐ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 09/15/2022
mm/dd/yyyy

Airframe Total Time: 2197.9 hrs

hours measured at (Select one)

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
- ☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: McCauley

Model: 1A170E/JHA7660

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: Artex

Model or Part No.: C406-N

TSO No.: ☐ OC91 (121.5 MHz) ☒ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated:

- Indicate Reason:**
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☒ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
- ☐ Airframe Parachute
- ☒ Angle of Attack Indicator
- ☒ Autopilot
- ☐ Data Recorder
- ☐ Electronic Flight Bag or Handheld Device
- ☒ Electronic Multifunction Display
- ☒ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☒ Onboard Weather
- ☐ Satellite Tracking Device
- ☒ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION			
Registered Aircraft Owner Name: <u>Auburn University</u> Fractional Ownership Aircraft: ☐ Yes ☒ No		City: <u>Auburn</u> State: <u>AL</u> ZIP: <u>36849</u> Country: <u>USA</u>	
Operator of Aircraft ☒ Same As Registered Owner Name: _____ Doing Business As: _____ Air Carrier/Operator Designator (4 Character Code): _____		☒ Same Address as Registered Owner City: _____ State: _____ ZIP: _____ Country: _____	
Operating Certificates Held <i>(Check all that apply)</i> ☐ None ☐ Flag Carrier Operating Certificate (FAR 121) ☐ Supplemental ☐ Air Cargo ☐ Foreign Air Carriers (FAR 129) ☐ Rotorcraft External Load (FAR 133) ☐ Commuter Air Carrier (FAR 135) ☐ On-Demand Air Taxi (FAR 135) ☐ Commercial Air Tour (FAR 136) ☐ Agricultural Aircraft (FAR 137) ☒ Pilot School (FAR 141) ☐ Certificate of Authorization or Waiver (COA) ☐ Commercial Space Transportation Experimental Permit ☐ Commercial Space Transportation License ☐ Other Operator of Large Aircraft	Regulation Flight Conducted Under ☒ FAR 91 ☐ FAR 129 ☐ FAR 415 ☐ FAR 103 ☐ FAR 133 ☐ FAR 431 ☐ FAR 121 ☐ FAR 135 ☐ FAR 435 ☐ FAR 125 ☐ FAR 137 ☐ FAR 437 ☐ FAR 91 Special Flight ☐ Non-US, Commercial ☐ Non-US, Non-commercial ☐ Public Aircraft <i>(Select one)</i> ☐ Armed Forces ☐ Federal ☐ State ☐ Local ☐ Unknown	Revenue Operation for FAR 121, 125, 129, 135 <i>(Select one for each group)</i> ☐ Scheduled or Commuter ☐ Domestic ☐ Non-Scheduled or Air Taxi ☐ International ☐ Passenger ☐ Cargo ☐ Mail Contract Only	
Revenue Sightseeing Flight ☐ Yes ☒ No		Purpose of Flight for FAR 91, 103, 133, 137 <i>(Select one)</i> ☐ Aerial Application ☐ Firefighting ☐ Unknown ☐ Aerial Observation ☐ Flight Test ☐ Air Drop ☐ Glider Tow ☐ Air Race/Show ☒ Instructional ☐ Banner Tow ☐ Other Work Use ☐ Business ☐ Personal ☐ Executive/Corporate ☐ Positioning ☐ External Load ☐ Skydiving ☐ Ferry	
AIRPORT INFORMATION <i>(Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)</i>			
Airport Name: <u>Moton Field Municipal Airport</u> Airport Identifier: <u>06A</u> Proximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/A		Distance From Airport Center: <u>< 1</u> sm Direction From Airport: <u>309</u> degrees true Airport Elevation: _____ ft. msl	
Runway Information Runway ID: <u>13</u> (L/R/C) Length: <u>5005</u> ft Width: <u>100</u> ft Runway/Landing Surface <i>(Check all that apply)</i> ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water ☐ Concrete ☐ Gravel ☐ Metal/Wood ☐ Dirt ☐ Ice ☐ Snow ☐ Unknown		Condition of Runway/Landing Surface <i>(Check all that apply)</i> ☒ Dry ☐ Snow-Compacted ☐ Water-Calm ☐ Holes ☐ Snow-Crusted ☐ Water-Choppy ☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy ☐ Rough ☐ Snow-Wet ☐ Wet ☐ Rubber Deposits ☐ Soft ☐ Slush-Covered ☐ Vegetation ☐ Unknown	
Approach/Departure Segment <i>(Select one)</i> ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach ☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☒ Go Around ☐ Initial Climb ☐ Aborted Landing (after touchdown) ☐ Crosswind ☐ Unknown			
IFR Approach <i>(Check all that apply)</i> ☒ None ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice ☐ SDF ☐ Sidestep ☐ LDA ☐ GPS ☐ VOR/TVOR ☐ ILS ☐ ASR ☐ VOR/DME ☐ Localizer Only ☐ Visual ☐ TACAN ☐ LOC-back course ☐ Contact ☐ RNAV ☐ Circling ☐ Unknown		VFR Approach <i>(Check all that apply)</i> ☐ None ☒ Traffic Pattern ☐ Stop and Go ☐ Straight-In ☐ Touch and Go ☐ Valley/Terrain Following ☐ Simulated Forced Landing ☒ Go Around ☐ Forced Landing ☐ Full Stop ☐ Precautionary Landing ☐ Unknown	

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☒ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying
☒ Yes
 ☐ No

"Flight Crewmember 1" Identification

First Name: Theodore
 City of Residence: Acworth
 Middle Initial: R
 State: GA
 ZIP: 30101
 Last Name: Rose
 Country: USA
 Age at time of Accident/Incident: 25
 Date of Birth: [REDACTED] *mm/dd/yyyy*
 Certificate Number: [REDACTED] CFI

Degree of Injury

☐ None
 ☐ Fatal
☒ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☐ Left
 ☐ Front
 ☐ Unknown
☒ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☒ Installed
☒ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) *(Check all that apply)*

☐ None
 ☒ Flight Instructor
 ☒ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☒ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☒ Without limitations/waivers
 ☐ Unknown
☐ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

10/20/2021
mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review

or Equivalent, Including
 FAR 121/135 Checks: 10/26/2021
mm/dd/yyyy

Flight Review Aircraft

Make: Cessna
 Model: 172S

Airplane Rating(s)

(Check all that apply)
☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)
☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)
☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)
☐ None
☒ Airplane Single-Engine
☐ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☒ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings

None

Student Endorsements *(Include dates)*

Flight Time <i>(Enter appropriate number of hours in each box)</i>	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	1,058.9	1,022.9	1024.1							
Pilot in Command (PIC)	978.7	977.5	978.7							
Time as Instructor	646.5	646.5	646.5							
This Make/Model										
Last 90 Days	115.6	115.6	115.6							
Last 30 Days	30.8	30.8	30.8							
Last 24 Hours	2.3	2.3	2.3							

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☒ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying

☐ Yes
 ☒ No

"Flight Crewmember 2" Identification

First Name: Melissa

City of Residence: Auburn

Middle Initial: V

State: AL ZIP: 36830

Last Name: Graham

Country: USA

Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy

Certificate Number: _____

Degree of Injury

☒ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☒ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☒ Installed
☒ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☐ Commercial
 ☐ US Military
☒ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☒ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☒ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☒ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

08/03/2021
 mm/dd/yyyy

Medical Certificate Limitations

Must wear corrective lenses.

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

07/27/2022
 mm/dd/yyyy

Flight Review Aircraft

Make: Cessna

Model: 162

Airplane Rating(s)

(Check all that apply)
☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)
☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)
☒ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)
☒ None
 ☐ Instrument Airplane
☐ Airplane Single-Engine
 ☐ Instrument Helicopter
☐ Airplane Multi-Engine
 ☐ Helicopter
☐ Gyroplane
 ☐ Glider
☐ Powered Lift
 ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)						
Crew Name and Address				Seat Occupied		Injury
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____				☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign				Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
Crew Name and Address				Seat Occupied		Injury
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____				☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign				Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)						
Name and Address		Seat	Injury	Restraint Type		Inflatable Restraints
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
						☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
						☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
						☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
						☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: 06A
 City: Tuskegee
 State: AL
 Country: USA

Time of Departure

Time: 1503
 Time Zone: CDT

Destination

Airport ID: 06A
 City: Tuskegee
 State: AL
 Country: USA

Type Flight Plan Filed

☒ None ☐ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR
 Activated? ☐ Yes ☒ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

☐ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☒ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☐ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence:

264 ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☒ Internet
☐ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☒ On-Board Weather

Weather Observation Facility

Facility ID: _____
 Observation Time: _____
 Time Zone: _____
 Distance from Accident Site: _____ nm
 Direction from Accident Site: _____ degrees true

Basic Conditions

☐ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☐ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

_____ ft agl

Ceiling

☐ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

_____ ft agl

Temperature: _____ (C) or _____ (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in. Hg
 or _____ MB

Wind Direction

☒ Variable

-or-
 Direction: _____ degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
 Speed: 9 kts

Wind Gusts

☐ Not Gusting

-or-
 Speed: 12 kts

Visibility _____ miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☐ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☐ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☐ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount Type
☐ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

Amount Type
☐ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

Type (Check all that apply) Severity
☐ None ☐ Light
☐ Clear Air ☐ Moderate
☐ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

N/A

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☐ Destroyed
☒ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Nose strut bent and deflected with missing connection points, propeller damage, firewall damage, cowling damage and separation, left main gear strut bent upward opposite jacking point on underside of strut, skin buckling, damage to left main brake rotor. Aircraft was moved from resting place prior to investigation, unknown if any of the damage was caused by this relocation.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

See Attached.

RECOMMENDATION (How could this accident/incident have been prevented?)**Operator/Owner Safety Recommendation**

N/A

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)**Was there Mechanical Malfunction/Failure?** ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Lycoming IO-360-L2A Engine, L-37423-51E. Experienced loss in RPMs with throttle advanced to full throughout the critical phase of flight (attempted go-around). Experienced engine responsiveness delays beyond 10 seconds and greater than delays in responsiveness in prior takeoffs. Engine performance prior to and following impact demonstrated impeded function.

Total Time/Cycles On Part2197.9 Hours

Cycles

Time Since This Part Inspected/Overhauled85.7 / N/A Hours**FUEL & SERVICES INFORMATION****Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

44 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT****Was an emergency evacuation of the aircraft performed?** ☐ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location**OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)****Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report04/05/2023*mm/dd/yyyy***Name of Pilot/Operator:** Theodore R Rose**Signature:** _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____ **Title:** _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY**NTSB Accident/Incident No.**ERA23LA159**Reviewed by NTSB Regional Office**ERA**Name of Investigator**Gretz**Date Report Received**4/5/23

October 27, 2022 N858AU Report (Instructor Pilot)

I inspected the aircraft after monitoring the learner completing the preflight, double checking the fuel and oil and looking for any signs of unnoticed elements from prior flights worth noting and reporting. The aircraft started up normally, no indication of issues. Run up was normal as well. Both magneto drops were within tolerances, with a 50 RPM drop on the left magneto and an 80 RPM drop on the right magneto, approximately. The engine did not show any indication of issues when idled on both magnetos, after checking them.

We conducted a normal crosswind takeoff departing Auburn. The takeoff did not seem noteworthy at the time. We had verified that we were aligned on the proper runway and the learner applied full power, then began making the appropriate callouts. I recall remarking on the sluggish power on the takeoff roll, however I assumed it was due to a slow application of power by the learner.

The learner and I flew the aircraft to 06A. The learner and I discerned that Runway 13 was preferable. We entered the pattern on the forty-five to the downwind at pattern altitude, entering in front of an aircraft based at that airfield that was turning into a left crosswind leg of the traffic pattern.

I was conducting an assessment of the learner in order to accredit them for having transferred into Auburn University with their Private Pilot Certificate. As such, I assigned the learner a short-field approach and landing for me to assess in accordance with Airman Certification Standards, as well as ensuring that the performance was suitable to the curriculum.

The first landing was within striking distance of the goal for the approach and landing, however required some adjustments to technique. I assisted the learner at the round out to ensure that we were longitudinally aligned with the centerline of the runway about the vertical axis of the aircraft as to not side-load the aircraft upon touchdown, due to winds trending to a left direct crosswind down final. We touched the aircraft down normally with no indication of damage or malfunction.

After the completion of the first landing, we taxied off of the runway and debriefed the landing after completing the appropriate checklist. The learner was noticeably distraught in regards to the landing and I elected to assist them on a second attempt in order to assist in showing the learner the technique changes to correct errors demonstrated.

The learner took off on Runway 13 with a soft-field takeoff technique, the power was sluggish, although not inherently alarming as it would be appropriate to slowly and smoothly add power for the takeoff technique assigned. We climbed per the soft-field takeoff specifications, removing flaps around the time we crossed the departure end of the runway. This was a little further than I would have expected, but something that, from my perspective, seemed to be

Theodore Russell Rose IV

CFI-I, AGI

October 29, 2022

caused simply by the delay in the rate at which the learner applied power whilst rolling down the runway.

As we turned into the downwind leg of the traffic pattern, I informed the learner that I would stay with them at the controls, to assist in the technique adjustments I had observed would be helpful based upon the prior landing. Once abeam our point of intended landing, the one thousand foot markers for Runway 13, we reduced the throttle to 1500 RPM's, added wing flaps to 10 degrees, and I assisted the learner in acquiring the sight picture from the horizon that I use to maintain an 80 knot descent for the remainder of the downwind leg. I noticed the learner seemed unfocused momentarily, whilst looking at the horizon, and redirected their attention to what to expect next. The learner apologized for momentarily "zoning out" for the second or two, and answered correctly to the inquiry. We then turned left base for the runway, reducing our airspeed back from 80 knots, and setting flaps to 20 degrees. We cleared the final leg of the traffic pattern to the right of the aircraft as well as clearing the opposite base leg, short final, and the runway for other traffic, then turned final.

While on final, flaps were increased to full, per the ACS. I assisted the learner in inputting the proper crosswind correction technique required to maintain longitudinal alignment down centerline and instructed that this wind correction would aid us in maintaining control and correct for wind drift, as well as yaw, caused by the crosswind on our final leg of the landing.

From the moment we applied wind correction, we addressed our sight picture in order to attain an appropriate sink rate down final. This was accomplished by reducing our throttle setting to attain a rate of descent that trended to 500 feet-per-minute, while maintaining 61 knots indicated airspeed. There is no weather reporting at the field, and there were no prior indications of gusting conditions to inform us of a need to increase our approach speed to account for a gust factor. The other aircraft in the pattern had turned base behind us as we continued down short-final to the runway.

We cleared the simulated 50 foot obstacle, as well as the runway threshold, at approximately 61 knots, with any slight oscillations being a result of minor turbulence that was not intense enough to destabilize our approach, nor interfere with our alignment directly on runway centerline.

As we approached our point of intended landing and, to the best of my recollection, within an estimated range of 10-40 feet above the runway surface, we encountered atmospheric conditions that destabilized the approach. The attitude of the aircraft was disrupted abruptly, causing a reduction in our indicated airspeed. As I was at the controls to assist already, I immediately initiated a go-around procedure. I applied power immediately to full as we were still low to the ground and would require as much thrust as quickly as possible in order to arrest our sink rate. I simultaneously manipulated the flight controls in order to attain straight and level while maintaining a pitch attitude that would not induce a stall based on my scan of our instruments and outside sight picture.

Immediately after the rapid application of the throttle to full whilst maintaining all

Theodore Russell Rose IV

CFI-I, AGI

October 29, 2022

necessary flight control inputs, our sink rate greatly increased, rather than being arrested whatsoever by the addition of full power. We sank as though the power setting had not only remained entirely unchanged but had decreased greatly. I did not have time to reference the engine instruments or the tachometer due to our rapid sink rate and distance from the runway surface, as I pitched to avoid an unrecoverable loss in airspeed.

I do not know if the learner was on the controls at this point, but had no indication that they were fighting against any of my control inputs in any way whatsoever, nor manipulating anything in the aircraft at all that would lead to the exacerbated sink rate we gained.

There was little to no distance from the ground, and we had not achieved any arrest to the sink rate whatsoever from the application full power with the throttle. It was becoming clear that we were not climbing while at the pitch attitude necessary to maintain a safe airspeed and still climb away from the ground.

Within seconds of applying full power, before I could reach to the flap handle to reduce flaps to 20° and continue the go-around procedure, our sink rate increased beyond recovery at our altitude above ground level and the left main, our upwind wheel, impacted the runway surface on centerline slightly beyond the thousand foot markers. The upward-deflection in the strut caused the aircraft to veer off to the left of the runway, diverting us off of centerline. Because of the firmness of the landing and the rapid pull to the left, I assumed we had blown a tire upon touchdown. I applied full right rudder input to attempt to maintain centerline to no avail, and did not have an opportunity to reach for and pull the throttle to idle from its setting of full power, as my hand had been dislodged from the throttle upon impact. The engine was not producing any sound to indicate it was even running, nonetheless running at the appropriate rate given that the throttle was still set to maximum, with no change made to the aircraft by either occupants. The propeller had almost entirely stopped spinning prior to entering the grass, only striking the grass four times with no prior propeller strike at any point.

The left main landing gear gave out on impact with runway centerline. Following that, the second impact I experienced from inside the aircraft, as we departed the runway into the grass, was the nosewheel collapsing. This occurred immediately prior to seeing the propeller strike the grass a total of four times. The tires of the aircraft appeared to be fully in tact after the impact. There were no skidding marks left on the runway from any lateral motion of the wheels relative to the inertia of the aircraft longitudinally down centerline, and the plane was not side-loaded to any extent on touchdown. The diversion of the aircraft sharply to the left of centerline upon touchdown was due to the structural damage of the landing gear upon impact.

At no point in the landing did the stall horn or angle of attack indicator sound or display in any capacity. The aircraft did not buffet at any point. Neither the learner, nor myself, ever saw the indicated airspeed decline, nor angle of attack increase, to a point at which the aircraft would be at risk of a stall based on the weight and balance calculated prior to the flight, the pitch attitude, and particularly the configuration of flaps and setting of full throttle. The propeller did not strike nor nosewheel collapse until the aircraft had traveled more than 50 feet from centerline

Theodore Russell Rose IV

CFI-I, AGI

October 29, 2022

diagonally and departed the runway, and the landing directly on the upwind main landing gear with no bounce or "porpoise" whatsoever.

To the best of my knowledge, when the throttle was set to full, the aircraft did not respond as such. I do not recall responsiveness in the engine from the full throttle input auditorily nor physically. The aerodynamics of controlling the aircraft were that of an aircraft with power reduced beyond the idled condition it had been in prior to the attempted go-around. The result was the exacerbation of the sink rate that had been completely stable prior to the abrupt atmospheric conditions leading to the execution of a go-around and input of full power. The addition of full power had no observable effect whatsoever, even with the full-flap configuration of the aircraft, on arresting or reducing the sink rate of the aircraft to the runway surface. The aircraft was not nose-high or slow enough to induce a stall, nor nose-low upon touchdown. The flight attitude upon and prior to impact would have been completely recoverable in a standard go-around procedure, had the engine responded to the power setting of the throttle control input at the time the go-around procedure was commenced.