

NTSB ERA23LA171

N7772B Struck Parked Aircraft N920AA
CINCINNATI MUNI/LUNKEN FLD

Photo Array



Photo 1: Left wing damage to N7772B



Photo 2: Close-up view of left wing damage to N7772B. Note damage required a form 337 for major repair.



Photo 3: View of right propeller damage to N920AA



Photo 4: Left engine and profile view of N920AA