



Photo 1 – Embry-Riddle Digital Photograph. Frontal View of the Airplane. Note the Partially Collapsed Right Main Landing Gear.



Photo 2 - Embry-Riddle Digital Photograph. Frontal View of the Airplane. Note the Split on the Top Center Portion of the Carbon Fiber Reinforced Polymer Molded Construction Fuselage From Just Forward of the Windshield to About ½ Way Along Nose Section Baggage Compartment Door.