



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA178



Photo 1 – View of Accident Airplane, Inverted, from Front Right (Courtesy of FAA)



Photo 2 – View of Accident Airplane, Inverted, from Rear Right - Note Damage to Rudder (Courtesy of FAA)



Photo 3 – View of Fuselage – Note Crush Damage (Courtesy of FAA)