



Photo 1 – View of bent wing spar (FAA Photo)




Photo 2 – View of hand pump showing minor leakage (FAA Photo)