

NTSB ERA23LA196

N5400S, ICP SRL Savannah S

Photo Array



Photo 1: Overview of the airplane at the accident site (Pilot Photo)



Photo 2: Overview of the right wing at the accident site (Pilot Photo)



Photo 3: View of the damage to the right wing and fuselage (Photo Courtesy of FAA)



Photo 3: View of damage to the vertical stabilizer (Photo Courtesy of FAA)